

Modern Equipment Company

369 W Western Ave. P.O. Box 993 Port Washington, WI 53074-0993 (262) 284-9431
FAX (262) 284-9433

RSP-5440-5030-3
Rev. 1 07/16/93

RECOMMENDED SPARE PARTS LIST

FOR

GEARING ASSEMBLY

5440-5030-3

(Quantities Shown are for One (1) Unit)

<u>Qty</u>	<u>Part No.</u>	<u>Description</u>	<u>Wt.</u>
1	2255-1000-2	Worm and Shaft Assembly	37.25
1	0006-0014-2	Bushing	7.5
1	0006-0015-2	Bushing	2.43
1	0019-0055-5	Bearing Handwheel Shaft	.75
3	0019-0056-5	Bearing Handwheel Shaft	3.75
1	0121-0016-2	Gear Worm Wheel	66.09
1	0067-0009-2	Pinion	11.26
1	0121-0137-2	Gear Bevel	30.56
1	0171-0046-2-157	Key	.08

The quantities shown may have to be increased based on the number of units you have, and the amount of use-hours per day. Other items may have to be added, based on your past experience or severity of use.