

Modern Equipment Company, Inc.

369 West Western Avenue P.O. Box 993 Port Washington, WI 53074-0993 (262) 284-9431
(262) 284-9433

RSP-5520-5001-3
REV. 1 10/18/93

RECOMMENDED SPARE PARTS LIST

FOR

GEARING ASSEMBLY

5520-5001-3

(Quantities Shown are for One (1) Unit)

<u>Qty</u>	<u>Part No.</u>	<u>Description</u>	<u>WT.</u>
1	2290-1000-2	Worm and Shaft Assembly	38.23
1	0006-0029-2	Bushing	17.29
1	0006-0030-2	Bushing	8.96
1	0019-0055-5	Bearing Handwheel Shaft	.75
1	0019-0056-5	Bearing Handwheel Shaft	1.25
2	0019-0150-5	Bearing	3
1	0121-0045-2	Gear Worm	126.14
1	0121-0042-2	Gear Bevel	12.95
1	0121-0135-2	Gear Miter	44.51
1	0171-0046-2-001	Key	.08

The quantities shown may have to be increased based on the number of units you have, and the amount of use-hours per day. Other items may have to be added, based on your past experience or severity of use.

H:\WORD50\RSP\5520-5001.doc