
RECOMMENDED SPARE PARTS LIST FOR "G" GEARING WITH HANDWHEEL

5650-5000-3

Quantities Shown are for One (1) Unit

The quantities shown may have to be increased based on the number of units you have, and the amount of use-hours per day. Other items may have to be added, based on your past experience or severity of use.

Quantity	Part Number	Description	Weight
1	2400-1000-2	Worm and Shaft Assembly	81.36
2	0006-0039-2	Bushing	33
2	0019-0159-5	Bearing	2
1	0019-0150-5	Bearing	1.5
1	0019-0154-5	Bearing	1.5
1	0121-0136-2	Gear Bevel	93.53
1	0121-0051-2	Gear Bevel	13.52
1	0171-0046-2-009	Key	.12
1	0171-0046-2-157	Key	.08



Modern Equipment Co., Inc.

369 West Western Avenue Port Washington, WI 53074

PH: (262) 284-9431 www.ModernEQ.com

